

Degradation of rail steel in S&C´s

Carsten Jörn Rasmussen, Banedanmark

Presented at Intelliswitch symposium, August 2017

banedanmark





Content:

- Degradation of steel components in S&C´s
- Maintenance
- Noise











Squat causing heavy impact in track





Squats in stock rail





Defect in weld





Corrugation






Isolation joint









Degradated transition zone nose/wing






Transition zone nose/wing





Transition from nose to wing












High Impact Forces





Deformations in nose of crossing








Degradation of nose of crossing




Deformations and cracks in nose of crossing



Squat like cracks in nose of crossing





Noise complaints because of bad geometry





Maintenance of steel components in crossings:

- Manual preventive grinding
- Grinding train
- Planning train
- Manual repair welding
- Exchange of components




Manual preventive grinding of lipping steel:





Automatic grinding with train:





Automatic planning of S&C:














Heavy degradated nose of crossing – to be exchanged!





Noise measuring close to wheel





High noise from track

means often that something is wrong!



Correlations between degradated steel components (eg. S&C´s) and noise.



Noise measurements in Banedanmark

Correlations between degradated steel components (eg. in S&C´s) and noise.

To detect degradation in an early stage to optimize maintenance activities – e.g. milling.

Any experiences with use of noise measurements?





NDT at transition zone nose/wing

- Visual test including photos
- Profile measurements with laser scanner "Calibri")
- Hardness measurements ("Eqoutip")
- Penetrant test of small cracks

